

Page Denied

Next 1 Page(s) In Document Denied

ROUTING			
TO:	NAME AND ADDRESS	DATE	INITIALS
1	Director/NPIC		
2	Room 6N106		
3			
4			
	ACTION	DIRECT REPLY	PREPARE REPLY
	APPROVAL	DISPATCH	RECOMMENDATION
	COMMENT	FILE	RETURN
	CONCURRENCE	INFORMATION	SIGNATURE
REMARKS:			
FROM: NAME, ADDRESS, AND PHONE NO.			DATE

SECRET

(Security Classification)





(See inside cover)

25X1

25X1

CONTROL NO. Z- 10312/82

Copy **28**


Warning Notice
 Intelligence Sources and Methods Involved
NATIONAL SECURITY INFORMATION
 Unauthorized Disclosure Subject to Criminal Sanctions


SECRET

(Security Classification)

Warning Notice
Intelligence Sources and Methods Involved
(WNINTEL) or (D)

NATIONAL SECURITY INFORMATION
Unauthorized Disclosure Subject to Criminal Sanctions

DISSEMINATION CONTROL ABBREVIATIONS

NOFORN-	Not Releasable to Foreign Nationals
NOCONTRACT-	Not Releasable to Contractors or Contractor/Consultants
PROPIN-	Caution-Proprietary Information Involved
USIBONLY-	USIB Departments Only
ORCON-	Dissemination and Extraction of Information Controlled by Originator
REL . . .	This Information has been Authorized for Release to . . .

SECRET

25X1

(c) NATIONAL PHOTOGRAPHIC INTERPRETATION CENTERPage 1 of 1Copy 28Attachment to Z-10312/82
NPIC/PEG (3/82)
2 PART GRAPHIC**POSTATTACK CLEAN-UP**

AR RAWDATAYN OILFIELD GAS AND OIL SEPARATION PLANT 2, KUWAIT

25X1

1. (S/D) SIGNIFICANCE: EXTENSIVE CLEAN-UP OPERATIONS ARE UNDERWAY AT AR RAWDATAYN OILFIELD GAS AND OIL SEPARATION PLANT 2. THE PLANT MAY NOW BE PARTIALLY OPERATIONAL (GRAPHIC 1 OF 2).

2. (S/D) REMARKS: THE FACILITY, WHICH WAS HEAVILY DAMAGED DURING AN IRANIAN AIR ATTACK IN EARLY OCTOBER 1981 (GRAPHIC 2 OF 2) [REDACTED] AT LEAST ONE FLARE TOWER (NOT ON GRAPHIC 1) IS BURNING OFF GAS TODAY INDICATING THAT THE FACILITY IS PARTIALLY OPERATIONAL. SOME REPAIRS PROBABLY HAVE BEEN MADE AT THE PLANT ALTHOUGH SOME EQUIPMENT DESTROYED IN THE STRIKE HAS NOT BEEN REPLACED. REPAIRS ON THE FOUR PRESSURIZED STORAGE TANKS PROBABLY HAVE BEEN COMPLETED, AS THE REVETMENTS AROUND THE TANKS HAVE BEEN BREACHED PROBABLY TO ALLOW SPILLAGE TO DRAIN. REMOVED EQUIPMENT INCLUDED THE FIVE HORIZONTAL LONG PRESSURE SEPARATION VESSELS, THE PIPELINE MANIFOLD SYSTEM, 15 VERTICAL SEPARATORS, FOUR HORIZONTAL SEPARATORS AND THREE PROBABLE SURGE TANKS. THE AREA AROUND THE PUMP HOUSE HAS BEEN CLEARED OF DAMAGED EQUIPMENT; AND THE PUMP HOUSE IS BEING REBUILT. THE NUMEROUS BREACHS IN THE SECURITY FENCE THAT WERE USED BY VEHICLES IN THE CLEAN-UP OPERATIONS HAVE NOT BEEN REPAIRED. DAMAGED EQUIPMENT AND POSSIBLY REPLACEMENT PARTS ARE IN AN AREA APPROXIMATELY ONE QUARTER OF A MILE TO THE NORTH OF THE PLANT (NOT ON GRAPHIC).

25X1

3. [REDACTED], COORDINATES 29-52-29N 047-43-22E

25X1

COMMENTS AND QUERIES REGARDING THIS BRIEFING BOARD MAY BE DIRECTED TO THE NPIC/PEG OPERATIONS OFFICER.

These notes have been prepared for briefing purposes only and should not be used for detailed analytical work. Their use should be restricted to the particular briefing board(s) they were prepared for and must be considered valid only for the reporting period as indicated by the date of issue.

25X1

WARNING NOTICE
Intelligence Sources
and Methods Involved

SECRET

25X1

Page Denied

Next 1 Page(s) In Document Denied